



Tungsten E full teardown

Written By: fscottcopeland





TOOLS:

- [T5 Torx Screwdriver](#) (1)
 - [iFixit Opening Tools](#) (1)
-

Step 1 — Teardown



- There are 4 torx screws in each corner. Undo them and take them out.

Step 2






- Slide a spudger in between the metal casing. Slide it all around the casing, releasing the back from the clips holding it in.

Step 3



- Prise up the case, using the spudger.

Step 4



- The Lcd connector is held in with a double lock connector, simply push the locks forward, and the cable will disconnect with the help if a spudger.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-19 11:44:48 PM.